

TO BE FILLED BY THE INSPECTING OFFICER
(ASST. ENGINEER)

Name of School : AMRITA VIDYALAYAM, Kottekkad, Palakkad.

1. Name of Officer : ARUN XAVIER
2. Location : Palakkad
3. Period for which the certificate is issued : 2023-2024
4. Types of buildings :

(RCC BUILDING)

**GROUND FLOOR-1328 M²(Class room-5 Nos)
FIRST FLOOR-1320 M²(Class room-13 Nos)
SECOND FLOOR-1320 M²(Class room-13 Nos)
SECOND FLOOR-1320 M²(Class room-11 Nos)**

5. Nature of defect, if any :
a) Foundation and basement :
b) Superstructure :
c) Doors and windows :
d) Wood work wrought and put up :
e) Roof :
f) Flooring :
g) Miscellaneous :

} NIL


6. Any major defects noticed which will render the building unsafe in any manner :
7. Whether maintenance work have been done properly : Yes
8. Whether the structure is sound for Conducting classes : Yes. The structure is found fit for conducting classes under normal wind and weather conditions

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure to flood etc.
2. Any additional observations, if deemed necessary for the certificate may be furnished separately with the certificate.

Certified that the school was inspected by me on 24/05/2023 and found fit to conduct classes for the period of Academic year 2023-2024 for the reasons stated above.

Place : Marutharode

Date : 25.05.2023



19/5/23
Signature

Designation

Assistant Engineer
L.S.G.D. Section
Marutharode Grama Panchayat


Principal
Amrita Vidyalayam
Palakkad-678 732


Manager
Amrita Vidyalayam
Palakkad-678 732