

No: D10/19-20/AE/LSGD/Myp


Kottakkad, Palakkad.

- 1. Name of Officer ... Reeja S. Raj
- 2. Location ... Kottakkad in Marutharode GP.
- 3. Period for which the Certificate is issued ... 2019-20
- 4. Types of building RC Building, 4f-1328m²
FF-1320m²
SF-1320m²
TF-1320m²
- 5. Name of defect, if any :- : NIL
- (a) Foundation and basement ...
- (b) Superstructure ...
- (c) Doors and windows ...
- (d) Wood work wrought and put up ...
- (e) Roof ...
- (f) Flooring ...
- (g) Miscellaneous ...
- 6. Any major defects noticed which will render the building unsafe in any manner ... : NIL
- 7. Whether maintenance work have been done properly ... : yes.
- 8. Whether the structure is sound for conducting classes ... : yes, structure is safe for conducting classes under normal weather condition.

Note: (1) The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure to flood etc.
 (2) Any additional observations if deemed necessary for the certificate may be furnished separately with the certificate.

Certified that the School was inspected by me on10/7/19..... and found fit to conduct classes for the period for the reasons stated above.

Date: 10/7/19
 Place: Marutharode



Signature: [Handwritten Signature]
 Assistant Engineer
 L.S.G.D. Section